



GOVERNOR

GREG BELL

Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

5	_	
Representativ	es Present During the Inspection:	
Company	Guy Davis Environmental Scientist	
MSHA	Pete Hess Environmental Scientist III	

Inspection Report

Permit Number:	C0150009		
Inspection Type:	COMPLETE		
Inspection Date:	Wednesday, May 26, 2010		
Start Date/Time:	5/26/2010 8:22:00 AM		
End Date/Time:	5/26/2010 10:17:00 AM		
Last Inspection:			

Inspector: Pete Hess, Environmental Scientist III

Weather: Warm, 50's F. Overcast.
InspectionID Report Number: 2372

Accepted by: jhelfric 6/21/2010

Permitee: PacifiCorp

Operator: ENERGY WEST MINING CO

Site: TRAIL MOUNTAIN MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Mineral Ownership

Types of Operations

3,538.98	Total Permitted	✓ Federal	✓ Undergroun
10.39	Total Disturbed	✓ State	Surface
	Phase I	☐ County	☐ Loadout
	Phase II	✓ Fee	Processing
	Phase III	☐ Other	☐ Reprocessii

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Trail Mountain Mine site remains in temporary cessation status.

All snow has melted off the site; a complete site inspection was made this day.

No compliance issues were identified.

Inspector's Signature:

Pete Hess, Environmental Scientist III

Inspector ID Number: 46

Date

Wednesday, May 26 2010



Permit Number: C0150009 Inspection Type: COMPLETE

Inspection Date: Wednesday, May 26, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓			
2.	Signs and Markers	✓			
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓			
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓	✓	
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓		✓	
10.	Slides and Other Damage	✓		✓	
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading		✓		
13.	Revegetation		✓		
14.	Subsidence Control	✓		✓	
15.	Cessation of Operations		✓		
16.8	a Roads: Construction, Maintenance, Surfacing				
16.	o Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit		V		
21.	Bonding and Insurance	~		V	
22.	Other	V		V	

Permit Number: C0150009
Inspection Type: COMPLETE

Inspection Date: Wednesday, May 26, 2010

Page 3 of 3

4.a Hydrologic Balance: Diversions

All diversions appeared capable of functioning as designed.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The first quarter of 2010 impoundment inspection for the Trail Mountain Mine sediment pond was completed on March 29, 2010 by John Christensen, P.E. in the State of Utah. There were no signs of instability or structural weakness noted during that inspection. The pond had 0.03 AF of sediment storage capacity remaining prior to reaching the 60 % cleanout elevation. As observed this day, there was no water volume in the pond; the bottom was muddy.

4.d Hydrologic Balance: Water Monitoring

Fourth quarter water monitoring data for the Trail Mountain Mine permit area has been uploaded into the Division permanent data base.

7. Coal Mine Waste, Refuse Piles, Impoundments

Any material generated during the cleanout of the Trail Mountain sediment pond is disposed of at the Cottonwood / Wilberg active waste rock site.

9. Protection of Fish, Wildlife and Related Environmental Issues

The most recent raptor survey for the Energy West Mines is currently being evaluated by Divison biologists.

10. Slides and Other Damage

The highwall burn area directly behind the ventilation fan building (shotcrete area) appears to be continuing to deteriorate.

14. Subsidence Control

The mine has been in temporary cessation since 2001. All subsidence is believed to have reached maximum deformation. The last longwall panel extracted was located between barrier pillars.

21. Bonding and Insurance

The current liability insurance remains in effect through August 28, 2010. The amount of reclamation bond in place is \$ 1,354,000. This surety is provided by the Travelers Casualty and Surety company of America # 1039089971. The Travelers has an A.M. Best rating of A+.

22. Other

The chain link barriers located outby the mine opening seals were observed as secure.